

12


CORROSION RESISTANT COATINGS

STEELCOTE MANUFACTURING COMPANY
3418 GRATIOT, ST. LOUIS, MISSOURI 63103-2990
(314) 771-8053

August 16, 1989

Mr. Robert Morby,
Chief RCRA Branch
U.S. Environmental Protection Agency
Region 7
726 Minnesota Avenue
Kansas City, KS 66101

Dear Mr. Morby:

The following necessary corrective actions are to be taken by Steelcote Manufacturing in the light of an E.P.A. inspection of August 8, 1989.

1. 40CFR268.50(a)(2)(I) Containers of hazardous waste were not clearly marked to identify its contents and the date of accumulation. As of August 11, 1989, all drums have been marked for identification and date of accumulation. This is part of hazardous training at Steelcote.
2. 40CFR262.34(c)(1) More than 55 gallons of hazardous waste were present in individual satellite accumulation areas. As of August 21, 1989, all of the hazardous waste will be moved to a central storage area. All personnel in the plant have been notified that there is to be no more than 55 gallons of hazardous waste in any one satellite storage area at any one time.

If you have any questions or comments about this effective action as purposed by Steelcote, please do not hesitate to call me. I appreciate your time.

Sincerely,

STEELCOTE MANUFACTURING COMPANY

James S. Moore

James Moore
Plant Manager

JM:lw

cc: St. Louis Regional Office
Missouri Department of Natural Resources
Division of Environmental Quality
8460 Watson Road
Suite 217
St. Louis, MO 63119

RECEIVED

AUG 21 1989

USEPA, RCRA Branch



R00353070
RCRA RECORDS CENTER

